

# **Xpress Pay Terminal®**



## Reduce Labor Costs, Increase Customer Convenience with the Most User-Friendly Pay Station in the Industry

Our self-pay terminal is a win-win for your business and your customers. It allows you to run more cars (up to 80 per hour per XPT°) and reduce labor costs while enabling on-the-go customers to quickly complete their own transactions. The XPT works for exterior, flex and full-service tunnels – anywhere you want the customer to self-pay. Up to eight XPTs are supported per site.

### **Features**

#### Increase sales and loyalty

- Sell monthly unlimited plans
- · Sell prepaids such as gift cards and "buy one get one" deals
- Display special menus, rewards, expiration dates and messages for loyalty club members
- Sell washes through partner gas stations with WashCAP module

#### Accept numerous forms of payment

- · Cash and coins
- Credit cards Quick and secure processing. Optional local approval mode allows transactions during internet failure. EMV available.
- Gift cards and other prepaids
- Barcodes and SmartCodes®

#### Protect your investment and information

- Weather-resistant
- · Color security camera
- · Internal heater
- · Solid-state memory backup



#### Manage your business

- Receive terminal-specific reports from SiteWatch®
- Get automated alerts
- Quickly, securely transfer data site-to-site with Multi-Site Replication

#### Improve customer satisfaction

- Self-serve
- User-friendly touchscreen with 15" optically bonded display



## **Ease of Ownership**

The XPT was recently redesigned for greater serviceability and supportability, ensuring limited downtime and hassle.

- Diagnose issues in 10 minutes or less
- Replace parts in 45 minutes or less
- Service XPT with fewer tools
- Easily identify connector locations to eliminate incorrect connections
- Easily view internal components when servicing the XPT with battery backed-up LED lights inside, activates when main door is open
- Update bill acceptor and firmware remotely
- Receive automatic alerts and bulletins about potential problems at any XPT









