

Xpress Pay Terminal[®]

Reduce Labor Costs, Increase Customer Convenience with the Most User-Friendly Pay Station in the Industry

Our self-pay terminal is a win-win for your business and your customers. It allows you to run more cars (up to 80 per hour per XPT[®]) and reduce labor costs while enabling on-the-go customers to quickly complete their own transactions. The XPT works for exterior, flex and full-service tunnels – anywhere you want the customer to self-pay. Up to eight XPTs are supported per site.

Features

Increase sales and loyalty

- Sell monthly unlimited plans
- Sell prepaids such as gift cards and "buy one get one" deals
- Display special menus, rewards, expiration dates and messages for loyalty club members
- Sell washes through partner gas stations with WashCAP module

Accept numerous forms of payment

- Cash and coins
- Credit cards Quick and secure processing. Optional local approval mode allows transactions during internet failure. EMV available.
- Gift cards and other prepaids
- Barcodes and SmartCodes[®]

Protect your investment and information

- Weather-resistant
- Color security camera
- Internal heater
- Solid-state memory backup



Manage your business

- Receive terminal-specific reports from SiteWatch®
- Get automated alerts
- Quickly, securely transfer data site-to-site with Multi-Site Replication

Improve customer satisfaction

- Self-serve
- User-friendly touchscreen with 15" optically bonded display



Ease of Ownership

The XPT was recently redesigned for greater serviceability and supportability, ensuring limited downtime and hassle.

- Diagnose issues in 10 minutes or less
- Replace parts in 45 minutes or less
- Service XPT with fewer tools


IKR


- Easily identify connector locations to eliminate incorrect connections
- Easily view internal components when servicing the XPT with battery backed-up LED lights inside, activates when main door is open
- · Update bill acceptor and firmware remotely
- Receive automatic alerts and bulletins about potential problems at any XPT











For more information, contact us at 800.336.6338 www.DRB.com